

	Hits	Search Text	DBs
1	924	249/192,194,208,211,216.ccls.	USPAT; US-PGPUB
2	134	frame and 1	USPAT; US-PGPUB
3	20	3558095.URPN.	USPAT
4	15664	frame same longitudinal same transverse	USPAT
5	19065	249/\$.ccls.	USPAT
6	95	4 and 5	USPAT
7	25857	vibrat\$3 with (frame support)	USPAT; US-PGPUB
8	17	1 and 4	USPAT; US-PGPUB
9	6	1 and 7	USPAT; US-PGPUB
10	65613	425/\$.ccls.	USPAT; US-PGPUB
11	0	7 and concrete	USPAT; US-PGPUB
12	465	7 and 10	USPAT; US-PGPUB
13	559	concrete same 7	USPAT; US-PGPUB
14	187	12 and 13	USPAT; US-PGPUB
15	14	4 and 14	USPAT; US-PGPUB
16	4	"4063859"	USPAT; US-PGPUB
17	5	"4776557"	USPAT; US-PGPUB

	Hits	Search Text	DBs
1	1	"20020071885"	USPAT; US-PGPUB
2	1329	425/432,456,421,254,260,452.ccls.	USPAT; US-PGPUB
3	77	(support\$3 plate platen) same (mold die) same (vibrat\$3 with rod)	USPAT; US-PGPUB
4	32	2 and 3	USPAT; US-PGPUB
5	402	(support\$3 plate platen) same (mold die) same (driving with rod)	USPAT; US-PGPUB
6	2	2 and 5	USPAT; US-PGPUB
7	777	(support\$3 plate platen) same (mold die) same (driving with shaft)	USPAT; US-PGPUB
8	1	5846576.URPN.	USPAT
9	6	("3210450" "3279021" "3379120" "3744950" "4456449" "5653934").PN.	USPAT
10	6	3279021.URPN.	USPAT
11	13	2 and 7 not 4	USPAT; US-PGPUB
12	525	(support\$3 plate platen) same (mold die) same (driving with shaft)	EPO; JPO; DERWENT
13	277	(support\$3 plate platen) same (mold die) same (driving with rod)	EPO; JPO; DERWENT
14	109	(support\$3 plate platen) same (mold die) same (vibrat\$3 with rod)	EPO; JPO; DERWENT
15	852	15 16 17	EPO; JPO; DERWENT
16	88634	B29c03\$ B29c043\$	EPO; JPO; DERWENT
17	91	18 and 19	EPO; JPO; DERWENT
18	0	concrete and 20	EPO; JPO; DERWENT
19	60707	b28b\$	EPO; JPO; DERWENT
20	73	18 and 22	EPO; JPO; DERWENT
21	3	pallet and 23	EPO; JPO; DERWENT
22	3	pallet and 18	EPO; JPO; DERWENT
23	1174	3 5 7	USPAT; US-PGPUB
24	38	pallet and 26	USPAT; US-PGPUB